

Clear Creek Identified Road Problems to Fix
observed by K.Smith, Fisheries Biologist

IDENT	DATE/TIME	Road Number	COMMENT2	STREAM	lat	long	Work_Type	Priority
Dampditch	03-OCT-11 10:09:50AM	9731	improve drainage- minimize failure risk	Clear	46.04896668	-115.6906388	Add pipe	Low
Addpipe	03-OCT-11 10:33:51AM	9731	300' long wet ditch- add pipe before Road 9731-3	Clear	46.05426027	-115.6921042	Add pipe	Moderate
HoleInRoad	03-OCT-11 10:49:07AM	9731	12"x8" near road center- road has cracked for 50'	Clear	46.0558416	-115.6925057	Reinforce road	Low
Ditchpond	03-OCT-11 11:36:59AM	9731	logs holding cutslope- add drainage	Clear	46.06148732	-115.6995335	Add pipe	Moderate
HoleInRoad2	03-OCT-11 12:34:24PM	9731	rodent holes in center and edge of road	Clear	46.05350808	-115.6888636	Fill holes	Very Low
Roadcutseep4	09-NOV-11 1:45:23PM	9735	seep created by road cut	Solo	46.03186861	-115.6980888	Add pipe	Low
Roadcutseep3	09-NOV-11 11:35:34AM	9706	seep created by road cut	MF Clear	46.02629959	-115.7210873	Add pipe	Low
Wetditch2	10-AUG-11 1:00:23PM	1106	wet ditch along road- add drainage	SF Clear	45.97274057	-115.7859376	Add pipe	Moderate
Wetditch	10-AUG-11 11:13:10AM	1106	wet ditch along road- add drainage	SF Clear	45.97860362	-115.790086	Add pipe	Low
StrmInRoad3	10-AUG-11 2:19:22PM	1106	small amount of water from ditch in road- fix	SF Clear	45.96537899	-115.7832404	Clean ditch	Low
SwampRd	11-JUL-11 10:16:45AM	1160D	150' of swamp on road; well vegetated	WF Clear	45.99524782	-115.8216656	Decommission	Moderate
SwampRd2	11-JUL-11 10:24:05AM	1160D	150' of swampy road up and down from point	WF Clear	45.9947201	-115.8223442	Decommission	Moderate
Pstream6	11-JUL-11 10:29:55AM	1160D	4' stream; no structure; constricted; fix- low pr	WF Clear	45.99449093	-115.8228448	Decommission	Low
Pstream7	11-JUL-11 10:47:39AM	1160D	18" perennial under logs; low pr remove xing	WF Clear	45.99540574	-115.8244528	Decommission	Low
Pstream8	11-JUL-11 10:50:46AM	1160D	12" perennial over road; erosion; fix; low pr	WF Clear	45.99540146	-115.824489	Decommission	Low
Pstream2	11-JUL-11 9:43:40AM	1160D	18" perennial stream under log structure	WF Clear	45.99815701	-115.8179153	Decommission	Low
Pstream3a	11-JUL-11 9:56:24AM	1160D	4' stream; no structure; correct drainage- widen	WF Clear	45.99803053	-115.8175356	Decommission	Low
Pstream3a	11-JUL-11 9:56:24AM	1160D	4' stream; no structure; correct drainage- widen	WF Clear	45.99803053	-115.8175356	Decommission	Low
Iseep	11-JUL-11 9:58:11AM	1160D	seasonal seap runs down road; some erosion	WF clear	45.99766022	-115.8182992	Decommission	Low
Wetroad3	11-JUL-12 1:02:58PM	77799	60' of wet road; some erosion; well vegetated	Brown Springs	46.06265877	-115.6560147	Add pipe	Low
Wetroad5	11-JUL-12 1:07:06PM	77799	150' of wet road; seepy but well vegetated	Brown Springs	46.06242609	-115.6555488	Add pipe	Low
Wetroad	11-JUL-12 12:24:37PM	77799	seepy ditch; water on road; stable	Brown Springs	46.06374708	-115.6594366	Add pipe	Low
Wetditch	11-JUL-12 12:45:21PM	77799	wet ditch 50' around this point	Brown Springs	46.06293211	-115.6577329	Fix drainage	Moderate
Wetroad2	11-JUL-12 12:55:16PM	77799	30' wet grassy road due to cut slope seep	Brown Springs	46.062727	-115.6561058	Add pipe	Low
Wetroad4	11-JUL-12 2:04:26PM	77799	30' wet road surface due to roadcut seep	Brown Springs	46.06541307	-115.6521954	Add pipe	Low
Seep-Rdcut4	12-JUL-11 11:35:59AM	9442A	water in road; small perennial stream	Hoodoo Cr	45.96850343	-115.8079357	Add pipe	Moderate
SeepRdcut5	12-JUL-11 12:30:06PM	9442	30' of road is wet caused by seep, vegetated	Hoodoo Cr	45.96973498	-115.8067801	Add pipe	Moderate
Pstream12	12-JUL-11 12:32:59PM	9442	12" perennial stream; need to add road drainage	Hoodoo	45.96929544	-115.8073438	Add pipe	Moderate
Wetditch	12-JUL-11 12:39:17PM	9442	ditch w/ standing water; ditch blocked by log	Hoodoo Cr	45.96946886	-115.8078468	Clean ditch	Moderate
Addpipe	12-JUL-11 12:47:04PM	9442	add pipe, ditch is deepening over time	Hoodoo Cr	45.96982216	-115.8082478	Add pipe	Moderate
Wetditch2	12-JUL-11 12:51:55PM	9442	ditch/road w/ standing water; ditch blocked by log	Hoodoo Cr	45.97024326	-115.8081851	Clean ditch	Moderate
Addxing	16-SEP-10 9:52:31AM	1855	water from seep needs to be directed under road	South Fork Clear Cr	45.94632827	-115.7666728	Add pipe	Moderate
Addxing2	16-SEP-10 9:58:36AM	1855	perennial flow from slump, get flow out of ditch	South Fork Clear Cr	45.94659967	-115.7664363	Add pipe	Moderate
FailureRd	20-JUL-11 10:50:11AM	9700	very large road fill failure down draw	Pilot Knob	46.07685621	-115.7209905	Fix failure?	Low
FillcrackRd	20-JUL-11 3:24:22PM	9700	additional fill ready to fail frm existing failure	Pilot Knob	46.07614199	-115.7224567	Fix failure	Moderate
Rdsrfcerosion	28-JUN-12 1:22:16PM	9732	200' of surface erosion on gravel road; 4" deep	Solo	46.04896551	-115.6997189	Fix drainage	High
Roadpotntlfail	28-JUN-12 1:33:50PM	9732	road failure beginning in fill slope- 3 down road	Clear	46.05351504	-115.7010958	Fix fill slope	High
Cleanditch	28-JUN-12 11:34:10AM	9730J	2 slumps cover ditch; flow on road surface	MF Clear	46.0472468	-115.7544418	Clean ditch	High
Addpipe2	28-JUN-12 11:38:05AM	9730J	seepy area above- ditch erosion moderate	MF Clear	46.04706022	-115.7535701	Add pipe	Moderate
Wetditch	28-JUN-12 12:19:31PM	9730J	puddle fed by seep, no failure risk	Solo	46.04641096	-115.7493137	Add pipe	Moderate
Addpipe3	28-JUN-12 2:07:38PM	9732	seepy ditch	Clear	46.05746895	-115.6994824	Add pipe	Moderate
SeepInRoad	28-OCT-11 1:02:38PM	1114	10" shallow perennial over road- add rolling dip	Brown Springs	46.0754084	-115.6921506	Add drain dip	Low
Roadcutseep	28-OCT-11 1:11:43PM	1114	draining okay but could be better- ditch over road	Brown Springs	46.07339985	-115.6930693	Add drain dip	Low
Roadcutseep2	28-OCT-11 1:14:20PM	1114	seep created by road cut	Brown Springs	46.07270918	-115.6921363	Add drain dip	Low
Roadfailure	28-OCT-11 1:23:28PM	1114	old slide created by seep above road- plugged pipe	Brown Springs	46.07056408	-115.6884934	Add drain dip	Moderate
SeepSlumpy	28-OCT-11 1:34:22PM	1114	seep created by road cut	Brown Springs	46.07128819	-115.6861149	Add drain dip	Low
PondOnRoad	28-OCT-11 11:57:29AM	1114	pond on inside ditch w/ some overflow	Brown Springs	46.07701429	-115.7024835	Add pipe	Low
Sinkhole	28-OCT-11 12:02:51PM	1114	road sink hole - unusual location on inside edge	Brown Springs	46.07688907	-115.7025708	Decommission	Low
SlumpTop	28-OCT-11 12:29:12PM	1114	top of slump caused by water on road- decom road	Brown Springs	46.07753162	-115.6928645	Decommission	Low